	Тур	L#	Hit s	Search Text	DBs	Time Stamp	Comments	Errord finition	Errors
1	BRS	L3	35	123/90.31 and (eccentric same cam same rocker same shaft)	USPA T; US-P GPUB; EPO; JPO; DERW ENT	2004/01/0 8 14:24			0
2	BRS	L2	75	123/90.17 and (eccentric same cam same rocker same shaft)	USPA T; US-P GPUB; EPO; JPO; DERW ENT	2004/01/0 8 14:29			0
3	BRS	L1	111	123/90.16 and (eccentric same cam same rocker same shaft)	USPA T; US-P GPUB; EPO; JPO; DERW ENT	2004/01/0 8 14:34			0
4	BRS	L4	37	(fuel near inject\$3) same (intake near manifold) same (valve near pressure)	USPA T; US-P GPUB; EPO; JPO; DERW ENT	2004/01/0 8 14:51			0
5	IS& R	L6	360	((123/184.42) or (123/184.53) or (123/184.47)).CCL S.	USPA T; US-P GPUB	2004/01/0 8 14:53			0

Typ e L #		DBs Time Stamp	Errord finition
6 R L5	(123/184.21).CCLS	USPA T; 2004/01 US-P 8 14:53 GPUB	/ 0 0